



#	Catalogue Part Number	Quantity	Description	List	Ext. List
1	ELV F-TSSL-3636	1	SQUARE-STAT TABLE,MEL,36"Wx36"D	\$1,608.00	\$1,608.00
2	SLO L-CCAB-Y-16	4	CANTILEVER ARM,16"DEEP,BLACK,INTERMEDIATE,FOR GALLERY PANEL	\$44.00	\$176.00
3	SLO L-CCAB-Y-22-L	2	CANTILEVER ARM,22"DEEP,BLACK,LEFT HAND,FOR GALLERY PANEL	\$70.00	\$140.00
4	SLO L-CCAB-Y-22-R	2	CANTILEVER ARM,22"DEEP,BLACK,RIGHT HAND,FOR GALLERY PANEL	\$70.00	\$140.00
5	SLO L-CRCL-226018-L	1	CREDENZA,22"HX60"WX18"D,LEFT HAND	\$1,288.00	\$1,288.00
6	SLO L-CRCL-226018-R	1	CREDENZA,22"HX60"WX18"D,RIGHT HAND	\$1,288.00	\$1,288.00
7	SLO L-CRCL-227218-L	1	CREDENZA,22"HX72"WX18"D,LEFT HAND	\$1,427.00	\$1,427.00
8	SLO L-CRCL-227218-R	1	CREDENZA,22"HX72"WX18"D,RIGHT HAND	\$1,427.00	\$1,427.00
9	SLO L-EH84-130	1	CONNECTOR HARNESS,8 WIRE,4 CIRCUIT,130L	\$416.00	\$416.00
10	SLO L-EM84-D	2	POWER MODULE,8 WIRE 4 CIRCUIT,DOUBLE SIDED,1/2/3/4	\$321.00	\$642.00
11	SLO L-ES84-168-O	1	STARTER HARNESS,NO MODULE,OPEN WIRE,168"L,8W,4C	\$487.00	\$487.00
12	SLO L-HC2W-180-A	3	PANEL CONNECTION,FOR 2 WAY STRAIGHT,TYPE A,SAME HEIGHT	\$23.00	\$69.00
13	SLO L-HOEG-Y-2824-L	2	LADDER END GABLE LEG,FOR GALLERY PANEL,28"Hx24"D,LH	\$489.00	\$978.00
14	SLO L-HOEG-Y-2824-R	2	LADDER END GABLE LEG,FOR GALLERY PANEL,28"Hx24"D,RH	\$489.00	\$978.00
15	SLO L-PAD-1836	2	SEAT PAD,18"Dx36"W,FABRIC WRAPPED,FOR 1 DRAWER LATERAL	\$511.00	\$1,022.00
16	SLO L-PAD-1860	2	SEAT PAD,18"Dx60"W,FABRIC WRAPPED,FOR 1 DRAWER LATERAL	\$698.00	\$1,396.00
17	SLO L-PPF0-3442-E	2	STANDARD PANEL,FABRIC,34"HX42"W,POWER CAPABLE	\$782.00	\$1,564.00
18	SLO L-PPF0-3448-N	2	STANDARD PANEL,FABRIC,34"HX48"W,NON-POWER CAPABLE	\$786.00	\$1,572.00
19	SLO L-WS0G-7224	4	STRAIGHT SURFACE,72"WX24"D,WITH GROMMET	\$457.00	\$1,828.00
				Total -	\$18,446.00



tayco®

SWITCH - TYPICAL FIFTEEN

www.tayco.com

(416) 252-8000

4/1/2025

1/1

It is the responsibility of the dealer to verify all dimensions, column locations, and other room features shown on the drawing are correct and meet the local building codes. Tayco will not accept responsibility for any error(s) in interpretation of this quotation, and strongly recommend a thorough review. Please notify Tayco of any discrepancies. This drawing is an intellectual property of Tayco and may not be copied, reproduced, distributed, or otherwise altered without prior written consent.