



#	Catalogue Part Number	Quantity	Description	List	Ext. List
1	SLO L-CRCL-226018-L	2	CREDENZA, 22"HX60"WX18"D, LEFT HAND	\$1,288.00	\$2,576.00
2	SLO L-CRCL-226018-R	2	CREDENZA, 22"HX60"WX18"D, RIGHT HAND	\$1,288.00	\$2,576.00
3	SLO L-ECK6	4	COMMUNICATION KIT TYPE 6-RJ45/45	\$160.00	\$640.00
4	SLO L-EH84-85	1	CONNECTOR HARNESS, 8 WIRE, 4 CIRCUIT, 85L	\$291.00	\$291.00
5	SLO L-EH84-D	2	POWER MODULE, 8 WIRE, 4 CIRCUIT, DOUBLE SIDED, 1/2/3/4	\$354.00	\$708.00
6	SLO L-ES84-168-0	1	STARTER HARNESS, NO MODULE, OPEN WIRE, 168"L, 8W, 4C	\$414.00	\$414.00
7	SLO L-HC2W-180-A	4	PANEL CONNECTION, FOR 2 WAY STRAIGHT, TYPE A, SAME HEIGHT	\$22.00	\$88.00
8	SLO L-HC4W-A	1	PANEL CONNECTION, FOR 4 WAY, TYPE A, SAME HEIGHT	\$143.00	\$143.00
9	SLO L-HCB1-P-L	2	CORNER BRACKET SUPPORT, LH, FOR STD PANEL, FOR 1" RECESSED WS	\$16.00	\$32.00
10	SLO L-HCB1-P-R	2	CORNER BRACKET SUPPORT, RH, FOR STD PANEL, FOR 1" RECESSED WS	\$16.00	\$32.00
11	SLO L-HCFM	4	CREDENZA TO WORKSURFACE FIXED SUPPORT	\$181.00	\$724.00
12	SLO L-HETF-34	4	END TRIM, FULL, 34"H, STANDARD	\$57.00	\$228.00
13	SLO L-HUFC-02	1	UNIVERSAL FILLER TOP CAP, 2"W X 2"D	\$9.00	\$9.00
14	SLO L-HWEG-P-2830-L	2	WRAP GABLE LEG, FOR STANDARD PANEL, 28"HX30"D, LH	\$481.00	\$962.00
15	SLO L-HWEG-P-2830-R	2	WRAP GABLE LEG, FOR STANDARD PANEL, 28"HX30"D, RH	\$481.00	\$962.00
16	SLO L-PAD-1830	4	SEAT PAD, 18"DX30"W, FABRIC WRAPPED, FOR 1 DRAWER LATERAL	\$359.00	\$1,436.00
17	SLO L-PPF0-3430-E	2	STANDARD PANEL, FABRIC, 34"HX30"W, POWER CAPABLE	\$502.00	\$1,004.00
18	SLO L-PPF0-3430-N	6	STANDARD PANEL, FABRIC, 34"HX30"W, NON-POWER CAPABLE	\$452.00	\$2,712.00
19	SLO L-VG-P-0860-F	4	PANEL MOUNTED SCREEN, 8"HX60"W, FROSTED TEMPERED GLASS	\$873.00	\$3,492.00
20	SLO L-WS00-6029	4	STRAIGHT SURFACE, 60"WX29"D	\$518.00	\$2,072.00
Total -				\$21,101.00	



tayco®

www.tayco.com

(416) 252-8000

3/31/2025

1/1

It is the responsibility of the dealer to verify all dimensions, column locations, and other room features shown on the drawing are correct and meet the local building codes. Tayco will not accept responsibility for any error(s) in interpretation of this quotation, and strongly recommend a thorough review. Please notify Tayco of any discrepancies. This drawing is an intellectual property of Tayco and may not be copied, reproduced, distributed, or otherwise altered without prior written consent.